

Inside dimension of
STM is 1.38"

Easily slide your PCS (portable
chuck spinner) or PFS (portable
fabrication station) into the STM and
lock using the T-bolt lock



The (STM) Spinner Table Mount with lock can be
bolted to your work table or welding rig